

Compliance Testing, Occupant Protection in Interior Impact, FMVSS 201P

Results of Pole Crash Tests, FY 2003

| FY   | LAB | Speed<br>km/h | Side<br>Struck | MY   | Make       | Model  | Pass/<br>Fail | Failure<br>Mode | HS#    |
|--|-----|---------------|----------------|------|------------|--------|---------------|-----------------|--------|
| <p>Legend: Fiscal Year (October 1, 2002 through September 30, 2003)</p> <p>Failures: P=performance, I=inspection, L=labeling</p> <p>HS#=report number</p> <p>A "Fail" result is the first indication of a possible non-compliance that will undergo further analysis by NHTSA. Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.</p> |     |               |                |      |            |        |               |                 |        |
| 2003   | EXI | 29            | Left           | 2002 | Saturn     | Vue    | Pass          |                 | 636470 |
| 2003   | MGA | 29            | Left           | 2003 | Honda      | Accord | Pass          |                 | 636509 |
| 2003   | MGA | 29            | Left           | 2003 | Volkswagen | Passat | Pass          |                 | 636554 |