

FEDERAL MOTOR VEHICLE SAFETY STANDARDS				
No.	STD	FMVSS TITLE	TYPE	MODE
1	101	Controls and Displays (Inspection)	Vehicle	Insp.-1
2	102	Transmission Shift Lever Sequence, etc. (I)	Vehicle	Insp.-2
3	103	Windshield Defrosting & Defogging Systems	Vehicle-1	TEST
4	104	Windshield Wiping & Washing Systems	Vehicle-2	TEST
5	105	Hydraulic Brake System	Vehicle-3	TEST
6	106	Brake Hoses	Equip.-1	TEST
7	108	Lamps, Reflective Devices, etc.	Equip.-2	TEST
8	109	Passenger Car New Pneumatic Tires	Equip.-3	TEST
9	110	Passenger Car Tire Selection & Rims	Vehicle-4	TEST
10	111	Rearview Mirrors	Vehicle-5	TEST
11	113	Hood Latch Systems (Inspection)	Vehicle	Insp.-3
12	114	Theft Protection	Vehicle-6	TEST
13	116	Hydraulic Brake Fluids	Equip.-4	TEST
14	117	Retreaded Pneumatic Tires (Inspection)	Equip	Insp.-4
15	118	Power Operated Window Systems	Vehicle-7	TEST
16	119	Truck/Bus New Pneumatic Tires	Equip.-5	TEST
17	120	Truck/Bus Tire Selection & Rims	Vehicle-8	TEST
18	121	Air Brake Systems	Vehicle-9	TEST
19	122	Motorcycle Brake Systems	Vehicle-10	TEST
20	123	Motorcycle Controls & Displays (Inspection)	Vehicle	Insp.-5
21	124	Accelerator Control Systems	Vehicle-11	TEST
22	125	Warning Devices	Equip.-6	TEST
23	126	Electronic Stability Control	Vehicle	TEST
24	129	Passenger Car New Non-Pneumatic Tires	Equip.-7	TEST
25	131	School Bus Pedestrian Safety Devices	Vehicle-12	TEST
26	135	Passenger Car Brake Systems	Vehicle-13	TEST
27	138	Tire Pressure Monitor System	Vehicle	Test
28	139	New Pneumatic Radial Tires	Equip	TEST
29	201	Occupant Protection in Interior Impact	Vehicle-14	TEST
30	202	Head Restraints	Vehicle-15	TEST
31	203	Impact Prot. for Driver from Strg. Control	Vehicle-16	TEST
32	204	Steering Control Rearward Displacement	Vehicle-17	TEST

FEDERAL MOTOR VEHICLE SAFETY STANDARDS				
No.	STD	FMVSS TITLE	TYPE	MODE
33	205	Glazing Materials (Inspection)	Equip	Insp.-6
34	206	Door Locks & Door Retention Components	Equip.-8	TEST
35	207	Seating Systems	Vehicle-18	TEST
36	208	Occupant Crash Protection	Vehicle-19	TEST
37	209	Seat Belt Assemblies	Equip.-9	TEST
38	210	Seat Belt Assembly Anchorages	Vehicle-20	TEST
39	212	Windshield Mounting	Vehicle-21	TEST
40	213	Child Restraint Systems	Equip.-10	TEST
41	214	Side Impact Protection	Vehicle-22	TEST
42	216	Roof Crush Resistance	Vehicle-23	TEST
43	217	Bus Window Retention & Release	Vehicle-24	TEST
44	218	Motorcycle Helmets	Equip.-11	TEST
45	219	Windshield Zone Intrusion	Vehicle-25	TEST
46	220	School Bus Rollover Protection	Vehicle-26	TEST
47	221	School Bus Body Joint Strength	Vehicle-27	TEST
48	222	School Bus Passenger Seating	Vehicle-28	TEST
49	223	Rear Impact Guards	Equip.-12	TEST
50	224	Rear Impact Protection (Inspection)	Vehicle	Insp.-7
51	225	Child Restraint Anchorage Systems	Vehicle-29	TEST
52	226	Ejection Migration	Vehicle	TEST
53	301	Fuel System Integrity	Vehicle-30	TEST
54	302	Flammability of Interior Materials	Equip.-13	TEST
55	303	Fuel System Integrity of CNG Vehicles	Vehicle-31	TEST
56	304	CNG Fuel Container Integrity	Equip.-14	TEST
57	305	Electric Vehicles	Vehicle-32	TEST
58	401	Interior truck Release	Vehicle	TEST
59	403	Platform Lift Systems	Vehicle	TEST
60	404	Platform Lift Installation	Vehicle	TEST
61	500	Low Speed Vehicle Requirements	Vehicle-33	TEST
SUMMARY: 37 vehicle standards, 17 equipment standards, 7 inspection standards				

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
Office of Vehicle Safety Compliance
COMPLIANCE STATUS REPORT
REPORT DATE: FEBRUARY 15, 2018

The following definitions are essential to the interpretation of the report:

INVESTIGATIONS —

CT (Compliance Test) — Investigations initiated based on the results of scheduled compliance test programs.

CI Number — OVSC Compliance Investigation Number (such as "**CI-208-020320**")

The CI number identifies FMVSS 208 with a test failure date of March 20, 2002. A compliance investigation is established when there is a reasonable expectation that a noncompliance may exist.

PE Number — OVSC Preliminary Evaluation Number (such as "**PE-214-020320**")

The PE number identifies FMVSS 214 with a test failure date, inspection date, complaint date, etc., of March 20, 2002. A preliminary evaluation action is taken to gather additional information in cases where there is only a possibility of a noncompliance.

The following types of investigations initiated as a result of information obtained from sources other than scheduled compliance test programs such as consumer complaints, industry disclosures, articles in the news media, etc:

IN (Inspection)	CP (Complaint)	MD (Manufacturer Defect)
ID (Part 574)	MI (Manufacturer Inquiry)	

COMPLIANCE TESTING —

TEST PROGRAM — Tests conducted in accordance with scheduled compliance test programs

RETEST — Retesting of items that have initially failed during a scheduled compliance test program

RESPONSIVE — Not a part of a scheduled compliance test program but consists of special testing, consumer complaint testing, etc.

COMPLIANCE TESTING LEGEND —

The following identifiers are used:

STD - Federal Motor Vehicle Safety Standard (FMVSS) or Regulation (i.e., Part 575, Part 567)

LAB - Testing laboratory under contract to OVSC

GRP - Test report group number. The following identifiers are found in the last character of the GRP number for those tests other than SCHEDULED compliance tests: R – Retest, T - Response test

SPECIAL CASES: FMVSS 109 - S=Test Program, R=Retest, C=Responsive
FMVSS 119 - A=Test Program, B=Retest, C=Responsive

US MFR/US DISTRIBUTOR - Manufacturer or distributor of motor vehicle or equipment item

MAKE - Make of motor vehicle or equipment item

MODEL - Information for motor vehicle or equipment item

STYLE/COMPONENT - Information for motor vehicle or equipment item

IDENTIFICATION NUMBER - Tire identification number

MY - Motor vehicle model year

HS NO. - Test report number used by the NHTSA Technical Information Services for identification purposes

RESULT - Test results (PASS or FAIL)

FAIL - P: performance failure
FAIL - I: inspection failure
FAIL - L: labeling or instruction failure

REPORTS ACCEPTED DURING JANUARY 2018 FOR FY 2017 TEST PROGRAM

A “FAIL” result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/GRP	MFR/DISTRIB	MY/MAKE/MODEL/STYLE	RESULT/HS NO.
201	MGA 006	NISSAN	2017 NISSAN TITAN CREW CAB PICK UP	FAIL 645400
206	MGA 21	MINITUBISHI	2016 MITSUBISHI OUTLANDER SIDE DOOR	PASS 645352
206	MGA 33	HYUNDAI KIA	2016 HYUNDAI KIA SEDONA SIDE DOOR	PASS 645354
206	MGA 34	JEEP	2016 JEEP GRAND CHEROKKEE LEFT FRONT DOOR	PASS 645353
208	MGA 001	CHRYSLER LLC	2017 CHRYSLER PACIFICA MPV 4-DOOR	PASS 645399
208	MGA 002	MAZDA	2017 MAZDA CX-3 MPV 4-DOOR	PASS 645355
208	MGA 005	GMC	2017 CHEVROLET SILVERADO CREW CAB PICK UP	PASS 645362
212	MGA 001	CHRYSLER LLC	2017 CHRYSLER PACIFICA MPV 4-DOOR	PASS 645399
212	MGA 002	MAZDA	2017 MAZDA CX-3 MPV 4-DOOR	PASS 645355
216	MGA 001	HONDA	2018 HONDA ODYSSEY MINIVAN 4-DOOR	PASS 645398
219	MGA 001	CHRYSLER LLC	2017 CHRYSLER PACIFICA MPV 4-DOOR	PASS 645399
219	MGA 002	MAZDA	2017 MAZDA CX-3 MPV 4-DOOR	PASS 645355
301	MGA 001	CHRYSLER LLC	2017 CHRYSLER PACIFICA MPV 4-DOOR	PASS 645399
301	MGA 002	MAZDA	2017 MAZDA CX-3 MPV 4-DOOR	PASS 645355

REPORTS ACCEPTED DURING JANUARY 2018 FOR FY 2018 TEST PROGRAM

A “FAIL” result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/GRP	MFR/DISTRIB	MY/MAKE/MODEL/STYLE	RESULT/HS NO.
110	GTL	ALFA ROMEO	2018 ALFA ROMEO GIULIA 4-DOOR SEDAN	PASS 645408
110	GTL	GMC	2018 BUICK REGAL 4-DOOR SEDAN	PASS 645409
110	STF	NISSAN	2018 NISSAN ALTIMA 4-DOOR SEDAN	PASS 645405
110	STF	TOYOTA	2018 TOYOTA RAV4 MPV 4-DOOR	PASS 645404

REPORTS ACCEPTED DURING JANUARY 2018 FOR FY 2018 TEST PROGRAM

A "FAIL" result is the first indication of a possible non-compliance issue that will undergo further analysis by NHTSA. **Consumers should continue to use a vehicle or equipment item unless notified by the manufacturer to stop.**

STD	LAB/ GRP	MFR/ DISTRIB	MY/MAKE/ MODEL/STYLE	RESULT/ HS NO.
111	GTL 004	VOLVO	2018 VOLVO XC60 MINIVAN 4-DOOR	PASS 645358
111	GTL 005	BMW	2018 BMW 5-SERIES 4-DOOR SEDAN	PASS 645366
111	GTL 006	TOYOTA	2018 TOYOTA CAMRY 4-DOOR SEDAN	PASS 645418
111	GTL 007	FIAT CHRYSLER	2018 DODGE RAM 1500 PICK UP TRUCK 4-DOOR	PASS 645417
126	TRC 001	CHRYSLER LLC	2018 JEEP WRANGLER 4-DOOR	PASS 645365
138	STF	BMW	2018 MINI COUNTRYMAN MPV 4-DOOR	PASS 645411
138	STF	FIAT CHRYSLER	2018 DODGE CHALLENGER 4-DOOR SEDAN	PASS 645412
138	STF	TOYOTA	2018 TOYOTA RAV4 MPV 4-DOOR	PASS 645413
226	MGA 003	VOLKSWAGEN	2018 VOLKSWAGEN TIGUAN MPV 4-DOOR	PASS 645363
226	MGA 1	SUBARU	2018 SUBARU CROSSTREK MPV 4-DOOR	PASS 645356
226	MGA 2	HONDA	2018 HONDA ODYSSEY MINIVAN 4-DOOR	PASS 645357

FAILURE LEGEND: P - PERFORMANCE; I - INSPECTION; L – LABELING

**COMPLIANCE INVESTIGATIONS (CIs) IN PROGRESS THROUGH JANUARY 2018
(CI NUMBER SYSTEM EXAMPLE: "CI-208-141220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2014)**

CI NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
CI-301-140512	Lion Bus/2013 Lion Bus/360 School Bus/Fuel spillage exceeded allowable amount	CT

CIs OPENED SINCE LAST REPORT

NONE

CIs CLOSED SINCE LAST REPORT

NONE

CAUSE:

PE Petition
CT Compliance Test
IN Inspection
CP Complaint
ID Part 574
MI Mfgr. Inquiry
MD Mfgr. Defect

**PRELIMINARY EVALUATION INVESTIGATIONS (PEs) IN PROGRESS THROUGH JANUARY 2018
(PE NUMBER SYSTEM EXAMPLE: "PE-208-141220" FOR FMVSS 208 WITH A
TEST FAILURE DATE OF DECEMBER 20, 2014)**

NONE

PEs OPENED SINCE LAST REPORT

CI NO.	MFR/MY/MAKE/MODEL/FAILURE	CAUSE
PE-221-160914	Starcraft Corporation/2014 Starcraft Prodigy Bus/Data Request	MI
PE-575-990610	Bridgestone/Firestone, Inc./1999 Bridgestone/Firestone Wilderness at/Performance	CP

PEs CLOSED SINCE LAST REPORT

CI NO.	MFR/MY/MAKE/MODEL/FAILURE
PE-221-160914	Starcraft Corporation/2014 Starcraft Prodigy Bus/Data Request/Closed by NHTSA 9/22/2017
PE-575-990610	Bridgestone/Firestone, Inc./1999 Bridgestone/Firestone Wilderness at/Performance/Closed by NHTSA 11/12/1999

CAUSE:

PE Petition
 CT Compliance Test
 IN Inspection
 CP Complaint
 ID Part 574
 MI Mfgr. Inquiry
 MD Mfgr. Defect